INSPECTION REPORT

Partial XXX Complete Exploration Inspection Date: 02/27/2003 / Time: 10:30 – 2:00
Date of Last Inspection: 01/29/2003

Mine Name: <u>Hiawatha Complex</u>	County: Carbon	Permit Number: <u>C/007/011</u>
Permittee and/or Operator's Name: Hiawat	ha Coal Company	
Business Address: P.O. Box 1245, Hunting	gton, Utah 84528	
Company Official(s): Alden Gustafson		
State Official(s): Dana Dean, Joe Helfrich	_Federal Official(s):	None
Weather Conditions: Clear, Temp 40° F		
Type of Mining Activity: Underground XX	X Surface Prep	PlantOther
Existing Acreage: Permitted 12,177 Distu	rbed 290 Regraded	Seeded
Status: Active Reclamation	_	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS	[X]		[X]	
3.	TOPSOIL				
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]			
b.	SEDIMENT PONDS AND IMPOUNDMENTS	\Box		\Box	
c.	OTHER SEDIMENT CONTROL MEASURES		\Box		
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS				
5.	EXPLOSIVES				
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box		\Box	
8.	NONCOAL WASTE				
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION				
12.	BACKFILLING AND GRADING				
13.	REVEGETATION				
14.	SUBSIDENCE CONTROL				
15.	CESSATION OF OPERATIONS	[X]		[X]	
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING				
b.	DRAINAGE CONTROLS				
17.	OTHER TRANSPORTATION FACILITIES				
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS				
19.	AVS CHECK (4 th Quarter- April, May, June)				\Box
20.	AIR QUALITY PERMIT		\Box		\Box
21.	BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT

(Continuation Sheet)

	(Continuation Sneet)	
PERM	IT NUMBER: <u>C/007/011</u> DATE OF INSPECTION: <u>02/27/200</u>	3
	(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)	
2.	SIGNS AND MARKERS	
	Viewed the ID signs at the public entrances into the permit area. The ID signs contained the appropriate information. The purpose of this visit was to conduct a partial inspection and obtain photos of the water-monitoring site above the Mohrland loadout.	
4D.	HYDROLOGIC BALANCE: WATER MONITORING	
	Photos of the mine water discharge to Cedar Creek were taken for entry in the database.	
15.	CESSATION OF OPERATIONS	
	Mr. Gustafson was informed of the notification requirements for temporary cessation of operation. The company plans on shipping slurry fines in the near future.	ıS.
Inspe	ctor's Signature: Date: February 28, 200	<u>3</u>
•	Joseph C. Helfrich #1	

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Elliot Finley, Hiawatha
Price Field office
O:\007011.HIA\Compliance\2003\p_0227.doc